



Restaura

Conservatie en restauratie van archeologische en historische voorwerpen
Windmolenven 45
6081 PJ Haelen

Certificate of Verification

XL3-37055V8B

Reading No 22
Mode General Metals
Time 2016-11-29 17:52
Duration 66.39
Units %
Sigma Value 2
Sequence Final
Alloy1 No Match : *7.11
Alloy2 No Match : *7.12
Flags
Project LE-PL-13
Vondstnummer 03454.001
Object Fles-kan
Positie Binnenzijde wand
Restauracode DIA 409
Opmerking



	%	±	Error
Sb	< LOD	:	0.044
Sn	*69.884	±	0.330
Cd	< LOD	:	0.028
Pd	< LOD	:	0.015
Ag	< LOD	:	0.035
Ru	< LOD	:	0.005
Mo	< LOD	:	0.004
Nb	< LOD	:	0.003
Zr	0.015	±	0.003
Bi	0.074	±	0.023
Pb	*22.088	±	0.114
Se	< LOD	:	0.014
Au	< LOD	:	0.002
W	< LOD	:	0.047
Zn	< LOD	:	0.016
Cu	0.171	±	0.017
Ni	< LOD	:	0.063
Co	< LOD	:	0.053
Fe	2.136	±	0.076
Mn	< LOD	:	0.101
Cr	< LOD	:	0.050
V	0.105	±	0.018
Ti	0.188	±	0.030
Al	< LOD	:	0.742
S	< LOD	:	0.002
P	0.927	±	0.035
Si	3.621	±	0.103
Mg	< LOD	:	0.002